

PERFORMANCE OF TRD MUMBAI DIVISION FOR THE
YEAR 2016-17

Sr.No.	Description	Unit	Qty
1	Steel Structure replacement work for less implantation /corroded in	MT	37.400
2	Removal redundant structure/Boom	No.	29
3	Removal of Auxilary catenary wire	Km	9.94
4	Replacemnt of Contact wire in	Km	25.082
5	Replacement of catenary wire in	Km	1.983
6	Scrap disposal (in MT)		
i	a) Ferrous item	MT	92.720
ii	b) Non ferrous item	MT	93.444