

PERFORMANCE OF TRD FOR MUMBAI DIVISION FOR THE YEAR 2018-19

| SN | Description | Unit | Qty |
|----|---|------|--------|
| 1 | Removal of critical implanatation structure | No | 141 |
| 2 | Removal of Leaning mast | No | 64 |
| 3 | Removal of redundatn portals | No | 385 |
| 4 | Removal of redundatn masts | No | 454 |
| 5 | Removal od redundatn 2.2KV / 22KV supermasts on OHE structures | No | 550 |
| 6 | Removal of redundatn foundations | No | 443 |
| 7 | Removal of corroded structures | No | 26 |
| 8 | Removal of PVC from Isolator jumper | No | 570 |
| 9 | Removal of PVC from Suspension points | No | 1535 |
| 10 | Removal of Redundant feeders crossing the lines | No | 16 |
| 11 | Removal of Redundant 2.2KV / 22KV cable on OHE structures | No | 536 |
| 12 | Replacement of OHE structures in Wet drain | No | 64 |
| 13 | Polarding /trimming of A , B & Ctype trees | No | 37749 |
| 14 | Removal of Bird nest | No | 3808 |
| 15 | Replacement of flashed insulator | No | 489 |
| 16 | Replacement of Broken insulator | No | 133 |
| 17 | Removal of Catenary Anchoring on ROB/FOB | No | 4 |
| 18 | Cleaning of foundation | No | 9102 |
| 19 | Muffing of OHE structure | No | 1052 |
| 20 | Painting of OHE structure | No | 2405 |
| 21 | Provision of Retrrreflective number plates | No | 6143 |
| 22 | Provision of Retrrreflective Boards | No | 1960 |
| 23 | Removal of 33KV & below Electrical crossing by converting them into underground cable | No | 22 |
| 24 | Removal of Auxiliary catenary wire | Km | 11.98 |
| 25 | Removal of Steel Structure | MT | 191.53 |
| 26 | Cleaning of Insulator by Jet machine | No | 30762 |
| 27 | Provision of LA Disconnecter | No | 322 |
| 28 | Provision of LA cover plate | No | 426 |
| 29 | SCRAP DISPOSAL | | |
| i | Ferrous item | MT | 831.34 |
| ii | Non ferrous item | MT | 120.94 |